



TEST REPORT RAPPORTO DI PROVA

Frontal impact on model TI-VAN Prova di urto frontale su allestimento TI-VAN

Customer (Richiedente):

- Dept./Firm (~~Ente~~/Società): TecnoIam S.r.l.
- Mr./Mrs (Sig./Sig.ra.): Luca Seccacini
- Address (Indirizzo): Via Flaminia 2/b, I- 61030 Calcinelli di Saltara (PU)

Test Request Form no.:
Modulo Richiesta Prova n.:

MEC15070.00

Test Report sent to:
Rapporto inviato a:

Mr. Luca Seccacini

Name and Signature of the test engineer:
Nome e Firma esecutore prova:

Pietro Vergani

Name and Signature of the Technical reviewer:
Nome e Firma del Revisore tecnico:

Maurizio Leone

Date of test samples receipt:
Data ricevimento campioni:

2015-02-10

Date of test execution:
Data esecuzione prove:

2015-04-10

Site of test execution (if different from the address in the footer):
Località esecuzione prove (se diversa dal piè pagina):

CSI S.p.A. V.le Lombardia, 20
I-20021 Bollate (MI)

Witness to the test:
Presenti alle prove:

Mr. Briscolini Renato

The test results contained in this Test report relate to the tested samples only.

I risultati del presente rapporto di prova si riferiscono esclusivamente al campione sottoposto a prova.

The integral reproduction of the present Test report is allowed; the partial reproduction must be authorized in writing by the Lab.
E' ammessa la riproduzione integrale del presente Rapporto di prova da parte del Richiedente; la riproduzione parziale dev'essere autorizzata per iscritto dal Laboratorio.

Form: ITA_F_09.01E (Rev.19 - October 13, 2014)

Test report n.: MEC15070.00_TR
Revision: 00
Document name: MEC15070.00_TR.doc

Project manager:
Maurizio Leone
Issue date: 2015-06-18

Phone: +39 0125 636911
Fax: +39 0125 636999
Maurizio.leone@tuv.it

TÜV Italia SRL
Divisione PS-CPS/COM
Via Montalenghe 8
I-10010 Scarmagno TO Italy



1	TEST SETUP <i>SETUP DI PROVA</i>	
1.1	SAMPLE IDENTIFICATION <i>IDENTIFICAZIONE CAMPIONE</i>	
1.1.1	Product/material subjected to test: <i>Prodotto/materiale sottoposto a prova:</i>	TI-VAN
1.1.2	Description: <i>Descrizione:</i>	Components installed in Vehicles
1.1.3	Level (Series product, prototype, etc.): <i>Livello (Prodotto di serie, prototipo, ecc.):</i>	Series
1.1.4	Part number: <i>Codice prodotto:</i>	not available
1.1.5	Serial number: <i>N° Matricola:</i>	not available
1.1.6	Sample identification code: <i>Codice identificativo del campione:</i>	not available
1.2	AUXILIARY DEVICES <i>DISPOSITIVI AUSILIARI</i>	/
1.3	TEST CONFIGURATION <i>CONFIGURAZIONE DI PROVA</i>	According to regulation ECE R17 Annex 9
1.4	DIAGNOSTIC SYSTEM <i>SISTEMA DIAGNOSTICO</i>	According to regulation ECE R17

Form: ITA_F_09.01E (Rev.19 - October 13, 2014)

Test report n.: MEC15070.00_TR
Revision: 00
Document name: MEC15070.00_TR.doc

Project manager:
Maurizio Leone
Issue date: 2015-06-18

Phone: +39 0125 636911
Fax: +39 0125 636999
Maurizio.leone@tuv.it

TÜV Italia SRL
Divisione PS-CPS/COM
Via Montalenghe 8
I-10010 Scarmagno TO Italy



2 TEST LIST

ELENCO DELLE PROVE

Test Description	Reference document	Standardized	Differences
2.1 Frontal impact <i>Impatto frontale</i>	ECE R17 Annex 9 - frontal impact	No	Impact speed = 31,5 km/h

Form: ITA_F_09.01E (Rev.19 - October 13, 2014)

Test report n.: MEC15070.00_TR
Revision: 00
Document name: MEC15070.00_TR.doc

Project manager:
Maurizio Leone
Issue date: 2015-06-18

Phone: +39 0125 636911
Fax: +39 0125 636999
Maurizio.leone@tuv.it

TÜV Italia SRL
Divisione PS-CPS/COM
Via Montalenghe 8
I-10010 Scarmagno TO Italy



3 TEST EQUIPMENT USED

APPARECCHIATURE UTILIZZATE

Test equipment of CSI laboratory

Test report no.0089\ME\CRH\15

4 ENVIRONMENTAL CONDITIONS

CONDIZIONI AMBIENTALI

4.1 ROOM TEMPERATURE
TEMPERATURA AMBIENTE

20,9 °C

4.2 RELATIVE HUMIDITY
UMIDITA' RELATIVA

Not detected

4.3 PRESSURE
PRESSIONE

Not detected

5 MEASUREMENT UNCERTAINTY

INCERTEZZA DI MISURA

Test report no.0089\ME\CRH\15

6 SAMPLING PLAN

PIANO DI CAMPIONAMENTO

Sample selected by the customer.



7 TEST AND/OR MEASUREMENT RESULTS

RISULTATI DELLE PROVE E/O MISURE

7.1 TEST N.1

PROVA N.1

Components series TI-VAN installed in FIAT SCUDO vehicle body

7.1.1 TEST OBJECTIVE

SCOPO DELLA PROVA

The FIAT SCUDO vehicle body, equipped with components for commercial vehicles TI-VAN, has been subjected to the same deceleration prescribed by regulation ECE R17 and directive 74/408/CE for the frontal impact

Impact speed = 31,5 km/h

Bags filled with sand ballast

Total load = 170 kg (supplied by the manufacturer)

7.1.2 TEST RESULTS

RISULTATI DI PROVA

The requirement 20 g / 30 ms is met

After the test, following was noted:

- no recognizable fractures of any of the safety relevant components
- no losing of attachment parts

Form: ITA_F_09.01E (Rev.19 - October 13, 2014)

Test report n.: MEC15070.00_TR
Revision: 00
Document name: MEC15070.00_TR.doc

Project manager:
Maurizio Leone
Issue date: 2015-06-18

Phone: +39 0125 636911
Fax: +39 0125 636999
Maurizio.leone@tuv.it

TÜV Italia SRL
Divisione PS-CPS/COM
Via Montalenghe 8
I-10010 Scarmagno TO Italy



8 REMARKS

NOTE

Test performed by CSI Laboratory under supervision of TÜV SÜD Italia

Test report no. 0089\ME\CRH\15

Form: ITA_F_09.01E (Rev.19 - October 13, 2014)

Test report n.: MEC15070.00_TR
Revision: 00
Document name: MEC15070.00_TR.doc

Project manager:
Maurizio Leone
Issue date: 2015-06-18

Phone: +39 0125 636911
Fax: +39 0125 636999
Maurizio.leone@tuv.it

TÜV Italia SRL
Divisione PS-CPS/COM
Via Montalenghe 8
I-10010 Scarmagno TO Italy

9 APPENDIX APPENDICE

9.1 PHOTO DOCUMENTATION DOCUMENTAZIONE FOTOGRAFICA



FIAT SCUDO vehicle body



TI-VAN before the test

Form: ITA_F_09.01E (Rev.19 - October 13, 2014)

Test report n.: MEC15070.00_TR
Revision: 00
Document name: MEC15070.00_TR.doc

Project manager:
Maurizio Leone
Issue date: 2015-06-18

Phone: +39 0125 636911
Fax: +39 0125 636999
Maurizio.leone@tuv.it

TUV[®]

TÜV Italia SRL
Divisione PS-CPS/COM
Via Montalenghe 8
I-10010 Scarmagno TO Italy



Italia



TI-VAN before the test



TI-VAN before the test

Form: ITA_F_09.01E (Rev.19 - October 13, 2014)

Test report n.: MEC15070.00_TR
Revision: 00
Document name: MEC15070.00_TR.doc

Project manager:
Maurizio Leone
Issue date: 2015-06-18

Phone: +39 0125 636911
Fax: +39 0125 636999
Maurizio.leone@tuv.it



TÜV Italia SRL
Divisione PS-CPS/COM
Via Montalenghe 8
I-10010 Scarmagno TO Italy



TI-VAN before the test



TI-VAN before the test

Form: ITA_F_09.01E (Rev.19 - October 13, 2014)

Test report n.: MEC15070.00_TR
Revision: 00
Document name: MEC15070.00_TR.doc

Project manager:
Maurizio Leone
Issue date: 2015-06-18

Phone: +39 0125 636911
Fax: +39 0125 636999
Maurizio.leone@tuv.it

TUV[®]

TUV Italia SRL
Divisione PS-CPS/COM
Via Montalenghe 8
I-10010 Scarmagno TO Italy



TI-VAN after the test



TI-VAN after the test

Form: ITA_F_09.01E (Rev.19 - October 13, 2014)

Test report n.: MEC15070.00_TR
Revision: 00
Document name: MEC15070.00_TR.doc

Project manager:
Maurizio Leone
Issue date: 2015-06-18

Phone: +39 0125 636911
Fax: +39 0125 636999
Maurizio.leone@tuv.it

TÜV Italia SRL
Divisione PS-CPS/COM
Via Montalenghe 8
I-10010 Scarmagno TO Italy



Italia



TI-VAN after the test



TI-VAN after the test

Form: ITA_F_09.01E (Rev.19 - October 13, 2014)

Test report n.: MEC15070.00_TR
Revision: 00
Document name: MEC15070.00_TR.doc

Project manager:
Maurizio Leone
Issue date: 2015-06-18

Phone: +39 0125 636911
Fax: +39 0125 636999
Maurizio.leone@tuv.it



TÜV Italia SRL
Divisione PS-CPS/COM
Via Montalenghe 8
I-10010 Scarmagno TO Italy



TI-VAN after the test



TI-VAN after the test

Form: ITA_F_09.01E (Rev.19 - October 13, 2014)

Test report n.: MEC15070.00_TR
Revision: 00
Document name: MEC15070.00_TR.doc

Project manager:
Maurizio Leone
Issue date: 2015-06-18


Phone: +39 0125 636911
Fax: +39 0125 636999
Maurizio.leone@tuv.it

TUV[®]

TÜV Italia SRL
Divisione PS-CPS/COM
Via Montalenghe 8
I-10010 Scarmagno TO Italy

9.2 ATTACHMENTS ALLEGATI

Vista Lato Passeggero



Form: ITA_F_09.01E (Rev.19 - October 13, 2014)

Test report n.: MEC15070.00_TR
Revision: 00
Document name: MEC15070.00_TR.doc

Project manager:
Maurizio Leone
Issue date: 2015-06-18

Phone: +39 0125 636911
Fax: +39 0125 636999
Maurizio.leone@tuv.it


TUV[®]

TÜV Italia SRL
Divisione PS-CPS/COM
Via Montalenghe 8
I-10010 Scarmagno TO Italy



Italia

Vista Lato Guida



Form: ITA_F_09.01E (Rev.19 - October 13, 2014)

Test report n.: MEC15070.00_TR
Revision: 00
Document name: MEC15070.00_TR.doc

Project manager:
Maurizio Leone
Issue date: 2015-06-18


Phone: +39 0125 636911
Fax: +39 0125 636999
Maurizio.leone@tuv.it

TÜV Italia SRL
Divisione PS-CPS/COM
Via Montalenghe 8
I-10010 Scarmagno TO Italy



Italia

Vista Lato Posteriore



Form: ITA_F_09.01E (Rev.19 - October 13, 2014)

Test report n.: MEC15070.00_TR
Revision: 00
Document name: MEC15070.00_TR.doc

Project manager:
Maurizio Leone
Issue date: 2015-06-18

Phone: +39 0125 636911
Fax: +39 0125 636999
Maurizio.leone@tuv.it

TÜV Italia SRL
Divisione PS-CPS/COM
Via Montalenghe 8
I-10010 Scarmagno TO Italy



10	SUMMARY	
	SOMMARIO	
1	TEST SETUP	2
1.1	SAMPLE IDENTIFICATION	2
1.2	AUXILIARY DEVICES	2
1.3	TEST CONFIGURATION	2
1.4	DIAGNOSTIC SYSTEM	2
2	TEST LIST	3
2.1	FRONTAL IMPACT	3
3	TEST EQUIPMENT USED	4
4	ENVIRONMENTAL CONDITIONS	4
4.1	ROOM TEMPERATURE	4
4.2	RELATIVE HUMIDITY	4
4.3	PRESSURE	4
5	MEASUREMENT UNCERTAINTY	4
6	SAMPLING PLAN	4
7	TEST AND/OR MEASUREMENT RESULTS	5
7.1	TEST N.1	5
8	REMARKS	6
9	APPENDIX	7
9.1	PHOTO DOCUMENTATION	7
9.2	ATTACHMENTS	13
10	SUMMARY	16

Form: ITA_F_09.01E (Rev.19 - October 13, 2014)

Test report n.: MEC15070.00_TR
Revision: 00
Document name: MEC15070.00_TR.doc

Project manager:
Maurizio Leone
Issue date: 2015-06-18

Phone: +39 0125 636911
Fax: +39 0125 636999
Maurizio.leone@tuv.it

TÜV Italia SRL
Divisione PS-CPS/COM
Via Montalenghe 8
I-10010 Scarmagno TO Italy